



1390 Roger Williams Way
North Kingstown, Rhode Island 02852

P: 401.667.0526
F: 401.667.0524

VAPOR TEST INSPECTION FORM

VESSEL: RTC 380

DATE: 04/17/2015

WORK ITEM: VAPOR TIGHTNESS TEST

PARAGRAPH: WI # 027

TEST METHOD: AIR PRESSURE TEST

LOCATION: CARGO TANKS 1,2,3,4 & VAPOR RECOVERY PIPING
Center

INSPECTION RESULTS: PERFORM AIR PRESSURE TEST @ 1 PSI AND
OBSERVE PRESSURE DROP FOR 60 MINUTES. PERFORM SOAP SPREY TEST. NO
LEAKS WERE FOUND IN PRESSURE RECOVERY PIPING AND TANK #1,2,3,4
CENTER LINE CARGO TANKS.

INSPECTOR PRINT: TOM MOWBRAY

INSPECTOR SIGNATURE:



CLIENT SIGNATURE:

